Environmental Inspection Form

Date/Time of Inspection/Inspector: 2/5/2016 / 9:00 A.M. / K. Acree

Additional Environmental Inspection Items

01. Has the new rock berm in front of E pond entrance been flattened due to road traffic and is it allowing water to run down the hill and not to pond E?		X	
02. Are there road conditions/ grading areas along the three ponds where water is not flowing toward the ponds?		Х	
03. Is water leaving through the outfalls of Pond D and E? Is the water approaching topping?	Х	Χ	
04. Does the Monthly SPCC plan created by Glover meet requirements?	Х		
05. Is there lack of rock or ash build-up within 70ft. of the entrance of:			
A) Pond ABC (2 entrances)		X	
B) Pond D (2 entrances)		Χ	
C) Pond E (1 entrance)		X	
06. Are there areas outside of operation that may be unstabilized and require stabilization?		Х	
07. Is the road dust suppression water fill tank clean and maintained?			Х
08. Is there ash build-up along Metal Pond road?		Χ	
09. Are there major erosion issues on the inner or outer sides of Dam road along Pond E?	Χ		
10. Is the drainage from the filtration system clear and properly sloped to Pond D?			Х
11. Is there any unauthorized material or flows in the Pond D emergency spillway?		Х	
12. Is the silt fence maintained and effective?	Х		
Comments Glover repaired hole in silt fence at Pond A.			
SWPPP:			
S107: Flow was contributed by stormwater (4.5 GPM) and the Pond D Toe Drain (13.5 GPM)			
S108: Standing water, due to 0.25 inch rain event on 2/3/2016, and there was a flow of 0.5 GPI	VI at	the f	ar west
section of outfall, near weir.			
Outfall 010: Combined stormwater and Pond D Toe Drain flow of 18 GPM. Appeared to have no	o unu	ısual	
conditions.			
No recordable rainfall in on-site rain gauge.			
Air temperature of 39°F and overcast skies (Quantico Marine Corps Airfield-website).			
1			

N/A